Greenlawn, Carriage Barn
Route 896 (North Broad Street),
.6 miles north of Middletown
Middletown
New Castle County
Delaware

HABS No. DE-215-C

HABS DEL, D-MIDTON, H-C-

PHOTOGRAPHS
REDUCED COPIES OF MEASURED DRAWINGS
WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

Form 10-920 (June 1983)

UNITEO STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS DEL; 2-MIDTON, 4-C-

ARCHITECTURAL DATA FORM

STATE	COUNTY New Castle	TOWN OR VICINITY	
Delaware		Middletown Vicinity	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)			
Greenlawn (family papers) carriage barn			С
SECONDARY OR COMMON NAMES OF STRUCTURE William Brady House; Ceorge Brady House			
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) East side of state route 896 (North Broad Street), .6 miles north of Middletown			
DATE OF CONSTRUCTION (INCLUDE SOURCE) ca. 1886 (construction; family papers) ARCHITECT(S) (INCLUDE SOURCE)			
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)			
The Creenlawn carriage barn was one of the finest examples of a domestic work structure incorporated into an overall Victorian domestic landscape scheme in southern New Castle County. The building was also a fine example of consolidated functional design.			
STYLE (IF APPROPRIATE) Carpenter Gothic			
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Sash and circular sawn braced frame on rubble masonry footings. Common rafter roof with butted joints at apex and scarfed through-purlins carried on diagonally set struts.			
HAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) see measured drawings.			
EXTERIOR FEATURES OF NOTE Steeply pitched cross-gable on southern elevation; scalloped cornice boards; open mounting area under central bay; board-and-batten doors hung on wrought strap hinges. Originally painted rust red with green trim. Sited to face north wall of house across drive leading past the house through formal gardens.			
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) See measured drawings for			
construction details. The design of the building included provision for carriage bays, mounting area, stables, open hay loft, corn crib and tack area. Box stalls in stable framed with plank nailed to diagonal earthfast struts nailed at top to joists.			
MAJOR ALTERATIONS AND ADDITIONS WITH DATES			
Early 20th-century garage lean-to addition made to east elevation (frame, one-story, weatherboarded): building demolished with all other associated structures in early July of 1985.			
PRESENT CONDITION AND USE			
Demolished July 1985			
OTHER INFORMATION AS APPROPRIATE			
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)			
National Register of History family papers			
Delaware Rural History Pro		or Historia DATE	
Architecture and Engineering	erman, Asst Director, Center fing, Univ. of Delaware	7-1-85	